BRUNSING ASSOCIATES, INC.

P.O. BOX 588 Windsor, CA. 95492

SURFACE ELEVATION:

Telephone: (707) 838-3027 Fax: (707) 838-4420

COORDINATES:

DATUM:

BORING NO.:

B-3

SHEET

1 OF 1

PROJECT:

COTATI STATION

Cotati, California LOCATION:

771 PROJECT NO.:

SMS LOGGED BY:

	SAMPLE INFORMATION					:	DESCRIPTION	WELL CONSTRUCTION		
	DEPTH FEET	LAB SAMPLE		BLOW COUNTS	Recovery (%)	PID (ppm)		STR	DETAIL	/1 V
	-						DARK BROWN CLAY (CL) dry to moist, medium stiff to stiff, ~20% silt, ~80% clay, trace coarse-grained sand			
	5- - - -			6 8 14		5.0				5-
	10- - -			15 12 12 12		5.0	BROWN CLAYEY GRAVELLY SILTY SAND (SM) moist, loose, ~20% gravel, ~50% very coarse to very fine-grained sand, ~20% silt, ~10% clay, subrounded gravel up to 22mm			10-
MPLETION 20050210.GPJ BACE.GDT 2/16/05	15-			24 33 29		10.0	BROWN CLAYEY SILTY SANDY GRAVEL (GC) wet, medium dense, ~70% gravel, ~10% very coarse to coarse-grained sand, ~10% silt, ~10% clay, angular gravel up to 36mm		\ \times_{\text{\tin}\ext{\texi{\text{\texi{\text{\tin}\tint{\text{\text{\text{\text{\text{\tin}}\tint{\text{\text{\tinit}\text{\text{\text{\text{\text{\text{\text{\tinit}\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\texi}\tint{\text{\texi}\tint{\text{\text{\texi}\tint{\text{\text{\texi}\titt{\text{\text{\text{\text{\teti}\tittt{\texi}\til\tint{\text{\tint}\tint{\text{\tint}\tinttitt	15-
NG LOG AND WELL CO	DRILL DRILL DRILL DRILL	LING CON LING MET LING EQU LING STAI	IPMENT:	6-inch	hollow s ock Dr10	_				
ENVIRONMENTAL BORING LOG AND WELL COMPLETION 2005	4	BRUNSING ASSOCIATES, INC. Appr.: Date:					ppr.: LOG OF E COTATI 8348 Sa Cotati	STAT Intero	ION Way	PLATE 6